

Technical Service Bulletin

COMPLIANCE:	SUGGESTED
SUBJECT:	Reported case of water intrusion
AFFECTED UNITS:	GPS-NEMA4-OE Shipped after 11/23/2020
DESCRIPTION:	There has been a reported case of water entry past the door gasket on a GPS-NEMA-4-OE. This could result is a possible shock hazard and equipment damage.

ACTIONS

- Inspect the position of the two enclosure latches. These should be turned a full 180 degrees and pushed down to seal the unit. Inspect the door gasket and mating surface for any damage or defects.
- Make sure the gasket makes contact with the mating surface when closing the door.
- Inspect the interior of the GPS-NEMA4-OE for water and evidence of past water intrusion.
- Ensure none of the components have been exposed to water. If evidence of water intrusion is found, disconnect power to the GPS-NEMA4-OE and contact GPS Air for further instructions.

ADDITIONAL COMMENTS

Contact GPS at info@gpsair.com

